


CENTURY MINE STREAM MITIGATION PHOTOGRAPHS
Piney Creek



Photograph: 48
PCSL-2: Successful Log vane and rock J-hook




Photograph: 49
PCSL-3: Unsuccessful bank grading, coir mat, and log



Photograph: 50
PCSL-4: Partially successful Coir log and live staking



Photograph: 51
PCSL-5: Unsuccessful live staking



Photograph: 52
PCSL-5: High Density Riparian Zone Planting



Photograph: 53
PCSL-7: Successful log vane and J-hook